H8SX Series, 1668R Group, UBC, USB, 24-bit Subclock Timer (TM32K), Boundary Scan, 4-ch EXDMAC FP-144L; Vcc= 3.0 to 3.6 volts, Temp= -20 to 75 C; Package: PLQP0144KA-A

Manufacturers	Renesas Technology Corp
Package/Case	144-LQFP
Product Type	MCU
RoHS	Green
Lifecycle	

Images are for reference only

Please submit RFQ for R5F61663RN50FPV or Email to us: sales@ovaga.com We will contact you in 12 hours.

RFQ

General Description

Ovaga has a large stock of R5F61663RN50FPV MCU from Renesas Technology Corp and we guarantee that they are original, brand new parts sourced directly from Renesas Technology Corp We can provide quality testing reports for R5F61663RN50FPV upon your request. To obtain a quote, simply fill in the required quantity, contact name, and email address in the quick quote form on the right. Our sales representative will contact you within 12 hours.

Related Products

R5F61664RN50FPV

Renesas Technology Corp

144-LQFP

R5F61668RN50FPV

Renesas Technology Corp

144-LQFP

ISL12022MIBZR5421

Renesas Technology Corp

SOIC-20 Wide

ISL12022MIBZ-TR5421

Renesas Technology Corp

SOIC-20 Wide

IS82C54-10Z

Renesas Technology Corp

PDIP-28

ICM7555IBAZ-T

Renesas Technology Corp

SOIC-8

CP82C84AZ

Renesas Technology Corp

PDIP-18

CS82C54-10Z

Renesas Technology Corp

PLCC-28

CP82C84AZ

Renesas Technology Corp

PDIP-18

CS82C54-10Z

Renesas Technology Corp

PLCC-28