

# **R5F61668RN50FPV**

Data Sheet

H8SX Series, 1668R Group, UBC, USB, 24-bit Subclock Timer (TM32K), Boundary Scan, 4-ch EXDMAC FP-144L; Vcc= 3.0 to 3.6 volts, Temp= -20 to 75 C; Package: PLQP0144KA-A

Manufacturers	Renesas Technology Corp	and the second sec
Package/Case	144-LQFP	State of the second sec
Product Type	Microcontrollers	
RoHS	Green	Images are for reference only
Lifecycle		
Diago guinit DEO	for R5F61668RN50FPV or <u>Email to us: sales@ovaga.com</u>	Wa will contract you in 12 hours

## **General Description**

Ovaga has a large stock of R5F61668RN50FPV Microcontrollers from Renesas Technology Corp and we guarantee that they are original, brand new parts sourced directly from Renesas Technology Corp We can provide quality testing reports for R5F61668RN50FPV upon your request. To obtain a quote, simply fill in the required quantity, contact name, and email address in the quick quote form on the right. Our sales representative will contact you within 12 hours.


### **Related Products**



R5F61664RN50FPV Renesas Technology Corp

144-LQFP

# <u>ISL12022MIBZR5421</u>





IS82C54-10Z Renesas Technology Corp PDIP-28



R5F61663RN50FPV Renesas Technology Corp

144-LQFP

### ISL12022MIBZ-TR5421



Renesas Technology Corp SOIC-20 Wide

### ICM7555IBAZ-T

Renesas Technology Corp SOIC-8 **RFO** 



### <u>CP82C84AZ</u>

Renesas Technology Corp

PDIP-18



Renesas Technology Corp PLCC-28

<u>CS82C54-10Z</u>