


H8SX Series, 1668R Group, UBC, USB, 24-bit Subclock Timer (TM32K), Boundary Scan, 4-ch EXDMAC FP-144L; Vcc= 3.0 to 3.6 volts, Temp= -20 to 75 C; Package: PLQP0144KA-A



Images are for reference only

Manufacturers	<a href="#">Renesas Technology Corp</a>
Package/Case	144-LQFP
Product Type	Capacitor Arrays
RoHS	
Lifecycle	

Please submit RFQ for R5F61664RN50FPV or [Email to us: sales@ovaga.com](mailto:sales@ovaga.com) We will contact you in 12 hours.




## General Description

Ovaga has a large stock of R5F61664RN50FPV Capacitor Arrays from Renesas Technology Corp and we guarantee that they are original, brand new parts sourced directly from Renesas Technology Corp We can provide quality testing reports for R5F61664RN50FPV upon your request. To obtain a quote, simply fill in the required quantity, contact name, and email address in the quick quote form on the right. Our sales representative will contact you within 12 hours.


## Related Products



[R5F61663RN50FPV](#)  
Renesas Technology Corp  
144-LQFP



[R5F61668RN50FPV](#)  
Renesas Technology Corp  
144-LQFP



[ISL12022MIBZR5421](#)  
Renesas Technology Corp  
SOIC-20 Wide



[ISL12022MIBZ-TR5421](#)  
Renesas Technology Corp  
SOIC-20 Wide



[IS82C54-10Z](#)  
Renesas Technology Corp  
PDIP-28



[ICM7555IBAZ-T](#)  
Renesas Technology Corp  
SOIC-8



[CP82C84AZ](#)

Renesas Technology Corp

PDIP-18



[CS82C54-10Z](#)

Renesas Technology Corp

PLCC-28